

# Hard Disk Drive

## SCSI Hard Disk

System Configuration				
Device Configuration		Manufacturer	Model No.	Spec.
	Processor	AMD	Athlon™ 64 Processor 3500+	FSB 200
	Memory	Apacer	SEC K4H280838C-TCB0	DDR266 /128MBx1
	VGA Card	MSI	MS-8815 Ver:1	
	Lan Card	Onboard(Realtek)	RTL 8110S	1Gbps
	Sound Card	Onboard(Realtek)	ALC850	8CH
	Hard Drive	As Follows		
	CD-ROM	SONY	CDU5211	52X
	Floppy Drive	Mitsumi	D353M3	1.44MB
	Power Supply	JouJye	JJ-300T	300W
	Mouse	Acer	M-S69	PS/2
	Keyboard	Acer	6511-CX	PS/2
Monitor	Viewsonic	G773	17" CRT	
SW Info	VGA BIOS	3.15.00.07		
	VGA Driver	2.9.5.8		

No.	Model	Capacity	SCSI Card
01	IBM	DNES-309170 (Ultra Wide)	Tekram DC-390U2W
02		DDYS-T36950 Ultra-160	Adaptec ASC-29160 Ver. B
03		Ultrastar IC35L036UWD210-0 Ultra-160	Adaptec ASC-39160 Ver. A
04		Ultrastar IC35L073UWD210-0 Ultra-160	Adaptec ASC-29160 Ver. B
05	QUANTUM	ATLAS 10K TN9100W Ultra-160	Adaptec ASC-39160 Ver. A
06		Atlas 10K III KW73L018 Ultra-160	Adaptec ASC-29160 Ver. B
07	SEAGATE	ST336706LW Ultra-160	Adaptec ASC-39160 Ver. A

No.	O.S. Installation	Result
01	OK	OK
02	OK	OK
03	OK	OK
04	OK	OK
05	OK	OK

No.	O.S. Installation	Result
06	OK	OK
07	OK	OK

## P-ATA Hard Disk

System Configuration				
Device Configuration		Manufacturer	Model No.	Spec.
	Processor	AMD	Athlon™ 64 Processor 3500+	FSB 200
	Memory	Apacer	SEC K4H280838C-TCB0	DDR266 /128MBx1
	VGA Card	MSI	MS-8815 Ver:1	
	Lan Card	Onboard(Realtek)	RTL 8110S	1Gbps
	Sound Card	Onboard(Realtek)	ALC850	8CH
	Hard Drive	As Follows		
	CD-ROM	SONY	CDU5211	52X
	Floppy Drive	Mitsumi	D353M3	1.44MB
	Power Supply	JouJye	JJ-300T	300W
	Mouse	Acer	M-S69	PS/2
	Keyboard	Acer	6511-CX	PS/2
	Monitor	Viewsonic	G773	17"CRT
SW Info	VGA BIOS	3.15.00.07		
	VGA Driver	2.9.5.8		

Model		Capacity	O.S. Installation	Driver Installation	Copy & Compare File	Result
Hitachi	7K250	HDS722525VLAT80	UD100 ; 250 GB	OK	OK	OK
	7K250	HDS724040KLAT80	UD133 ; 400 GB	OK	OK	OK
IBM	75GXP	DTLA-307075	UD100 ; 76.8 GB	OK	OK	OK
	60GXP	IC35L060AVER07-0	UD100 ; 61.5 GB	OK	OK	OK
	120GXP	IC35L080AVVA07-0	UD100 ; 82.3 GB			
		IC35L120AVVA07-0	UD100 ; 123.5 GB	OK	OK	OK
Maxtor	DiamondMax Plus D740X	D740X-6L(6L060J3)	UD133 ; 60 GB	OK	OK	OK
		D740X-6L(6L080J4)	UD133 ; 80 GB	OK	OK	OK
	DiamondMax D540X-4G	4G120J6	UD133 ; 120 GB	OK	OK	OK
		4G160J8	UD133 ; 160 GB	OK	OK	OK
	Fireball 3	2F040J0	UD133 ; 40 GB			
	DiamondMax 16	4R060J0	UD133 ; 60 GB	OK	OK	OK
		4R060L0	UD133 ; 60 GB	OK	OK	OK
		4A160J0	UD133 ; 160 GB	OK	OK	OK
		4A250J0-1A	UD133 ; 250 GB			
	DiamondMax Plus 8	6E040L0-1A	UD133 ; 40 GB			
MaxLine Plus II ATA	7Y250P0	UD133 ; 250GB	OK	OK	OK	
Quantum	Fireball Plus	AS40000AT	UD100 ; 40 GB	OK	OK	OK
		AS60000AT	UD100 ; 60 GB	OK	OK	OK
Samsung		SP4002H	UD100 ; 40 GB	OK	OK	OK
		SV0602	UD100 ; 60 GB	OK	OK	OK
		SV0802N	UD133 ; 80GB			

		SP0802N	UD133 ; 80GB	OK	OK	OK	OK
		Sp1203N	UD133 ; 120GB	OK	OK	OK	OK
		SP1604N	UD133 ; 160 GB	OK	OK	OK	OK
Seagate	Barracuda ATA III	ST340824A	UD100 ; 40 GB	OK	OK	OK	OK
	U Series	ST340823A	UD100 ; 40 GB	OK	OK	OK	OK
	Barracuda ATA IV	ST360021A	UD100 ; 60 GB	OK	OK	OK	OK
		ST380021A	UD100 ; 80 GB	OK	OK	OK	OK
	Barracuda ATA V	ST380023A	UD100 ; 80 GB	OK	OK	OK	OK
		ST3120023A	UD100 ; 120 GB	OK	OK	OK	OK
	Barracuda 7200.7	ST380011A	UD100 ; 80 GB	OK	OK	OK	OK
ST3160023A		UD100 ; 160 GB	OK	OK	OK	OK	

Model		Capacity	O.S. Installation	Driver Installation	Copy & Compare File	Result
WD	Special Edition	Caviar 1200JB	UD100 ; 120 GB	OK	OK	OK
		Caviar 2500JB	UD100 ; 250 GB	OK	OK	OK
	High-performance	Caviar 1200BB	UD100 ; 120 GB	OK	OK	OK
		Caviar 1800BB	UD100 ; 180 GB	OK	OK	OK
		Caviar 2000BB	UD100 ; 200 GB	OK	OK	OK

## S-ATA Hard Disk

System Configuration			
	Manufacturer	Model No.	Spec.
Device Configuration	Processor	AMD	Athlon™ 64 Processor 3500+ FSB 200
	Memory	Apacer	SEC K4H280838C-TCB0 DDR266 /128MBx1
	VGA Card	MSI	MS-8815 Ver:1
	Lan Card	Onboard(Realtek)	RTL 8110S 1Gbps
	Sound Card	Onboard(Realtek)	ALC850 8CH
	Hard Drive	As Follows	
	CD-ROM	ASUS	CD-S500-A 50X
	Floppy Drive	Mitsumi	D353M3 1.44MB
	Power Supply	JouJye	JJ-300T 300W
	Mouse	Acer	M-S69 PS/2
	Keyboard	Acer	6511-CX PS/2
	Monitor	Viewsonic	G773 17"CRT
SW Info	VGA BIOS	3.15.00.07	
	VGA Driver	2.9.5.8	

Model			Capacity	O.S. Installation	Shutdown 10x	Driver Installation	Copy & Compare File	Result
Hitachi		HDS722580VLSA80	UD150 ; 80GB	OK	OK	OK	OK	OK
		HDS722516VLSA80	UD150 ; 160GB	OK	OK	OK	OK	OK
		HDS724040KLASA80	UD150 ; 400GB	OK	OK	OK	OK	OK
Maxtor	DiamondMax Plus 9	6Y080M0	UD150 ; 80 GB	OK	OK	OK	OK	OK
	MaxLine Plus II SATA150	7Y250M0	UD150 ; 250GB	OK	OK	OK	OK	OK
Samsung		SP1612C	UD150 ; 160 GB	OK	OK	OK	OK	OK
Seagate	Barracuda Serial ATA V	ST380023AS	UD150 ; 80 GB	OK	OK	OK	OK	OK
WD	Enterprise	WD360	UD150 ; 36 GB	OK	OK	OK	OK	OK
		Caviar WD2500JD	UD150 ; 250GB	OK	OK	OK	OK	OK